

Ldrive14

WIRING

Connector Description



Pin	Symbol	Description
1	L	AC Input Line
2	N	AC Input Neutral
3	WW-	Warm White-
4	WW+	Warm White+
5	CW-	Cool White-
6	CW+	Cool White+

Wiring

The wiring can be in stranded wires with ferrules or solid with a cross section of 16-18AWG (0.75-1.5sq.mm). Strip 8.5- 9.5 mm of insulation from the cables to ensure perfect operation of the push-wire terminals. Use one wire for each terminal connector.

